

Stress-strain hysteresis curve diagram Figure 1:

വ

5




Figure 2






Figure 3

10



56






Figure 5






Figure 8



5



crimp stretch factor (%) = $(L_1 - L_2)/L_1 \times 100$ (%)

heat treatment: 15 mins in boiling water + 15 mins dry heat at 180°C

Figure 10




Figure 11

_